

Release notes

# Multisite System Manager

Version v3.1

9 March 2026

# Contents

---

1. Overview	1
2. Build: 3.15	2
2.1. Build: 3.15	2
2.2. Resolved issues	3
2.3. Known issues	3
3. Build: 3.14	2
3.1. Build: 3.14	2
3.2. Resolved issues	3
3.3. Known issues	3
4. Build: 3.13	2
4.1. Build: 3.13	2
4.2. Resolved issues	3
4.3. Known issues	3
5. Build: 3.12	2
5.1. Build: 3.12	2
5.2. Resolved issues	3
5.3. Known issues	3
6. Build: 3.11	2
6.1. Build: 3.11	2
6.2. Resolved issues	3
6.3. Known issues	3
7. Build: 3.10	2
7.1. Build: 3.10	2
7.2. Resolved issues	3
7.3. Known issues	3
8. Build: 3.08	2
8.1. Build: 3.08	2
8.2. Resolved issues	3
8.3. Known issues	3
9. Build: 3.07	2
9.1. Build: 3.07	2
9.2. Resolved issues	3
9.3. Known issues	3
10. Build: 3.06	2
10.1. Build: 3.06	2
10.2. Resolved issues	3
10.3. Known issues	3
11. Build: 3.05	2

11.1. Build: 3.05	2
11.2. Resolved issues	3
11.3. Known issues	3
12. Build: 3.04	2
12.1. Build: 3.04	2
12.2. Resolved issues	3
12.3. Known issues	3
13. Build: 3.03	2
13.1. Build: 3.03	2
13.2. Resolved issues	3
13.3. Known issues	3
14. Build: 3.02	2
14.1. Build: 3.02	2
14.2. Resolved issues	3
14.3. Known issues	3
15. Build: 3.01	2
15.1. Build: 3.01	2
15.2. Resolved issues	3
15.3. Known issues	3
16. Build: 3.0	2
16.1. Build: 3.0	2
16.2. Resolved issues	3
16.3. Known issues	3

# 1. Overview

The release notes provide an overview of the new features, enhancements, resolved, and known issues of the latest version and build of the Multisite System Manager.

## 2. Build: 3.15

### 2.1. Build: 3.15

#### 2.1.1. New feature

This Multisite System Manager release does not have any new features.

#### 2.1.2. Enhancement/Improvement

This Multisite System Manager release does not have any enhancement/improvement.

#### 2.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.15

  

Design software component	Version
Philips Dynalite System Designer	v4.48.7

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.48.7
Philips Dynalite Enabler app (iOS)	v3.19.0
Philips Dynalite Enabler app (Android)	v3.19.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.48.24642
PDDEG-S v3	v2.22.24664
PDDEG-S module	v1.0.45605
PDZG-E V2	v2.17.01

## 2.2. Resolved issues

The following issue is resolved in this Multisite System Manager release.

### 2.2.1. Sorting issue of the Test result column

This fix ensured that sorting in the **Emergency Tests** tab worked correctly.

## 2.3. Known issues

### 2.3.1. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

## 3. Build: 3.14

### 3.1. Build: 3.14

#### 3.1.1. New feature

##### PDZG-E Wireless Gateway

Introduced a PDZG-E Wireless Gateway into the existing Multisite System Manager to enhanced connectivity and improved feature support.

#### 3.1.2. Enhancement/Improvement

This Multisite System Manager release does not have any enhancement/improvement.

#### 3.1.3. Supported infrastructure

##### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.14

  

Design software component	Version
Philips Dynalite System Designer	v4.48.5

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.48.5
Philips Dynalite Enabler app (iOS)	v3.18.0
Philips Dynalite Enabler app (Android)	v3.18.0

##### Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.47.23964
PDDEG-S v3	v2.21.23974
PDDEG-S module	v1.0.45605
PDZG-E V2	v2.16.01

## 3.2. Resolved issues

This Multisite System Manager release does not have any resolved issues.

## 3.3. Known issues

### 3.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 3.3.2. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

## 4. Build: 3.13

### 4.1. Build: 3.13

#### 4.1.1. New feature

This Multisite System Manager release does not have any new features.

#### 4.1.2. Enhancement/Improvement

Emergency tests UI and PDF report

This improvement ensures that the emergency test UI and PDF report now include all drivers, including those for which no emergency tests are performed.

Redeploying multiple sites

This improvement ensures accurate and reliable redeployment of multiple sites.

#### 4.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.13

  

Design software component	Version
Philips Dynalite System Designer	v4.48.4

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.48.4
Philips Dynalite Enabler app (iOS)	v3.18.0
Philips Dynalite Enabler app (Android)	v3.18.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.47.23964
PDDEG-S v3	v2.21.23974
PDDEG-S module	v1.0.45605

## 4.2. Resolved issues

The following issue is resolved in this Multisite System Manager release.

### 4.2.1. Incorrect Notional energy data

This fix ensures timely and up-to-date **Notional** energy data is displayed in the **Energy dashboard**.

## 4.3. Known issues

### 4.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 4.3.2. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 5. Build: 3.12

## 5.1. Build: 3.12

### 5.1.1. New feature

This Multisite System Manager release does not have any new features.

### 5.1.2. Enhancement/Improvement

Editing Draft schedule for failed deployment

This improvement ensures that you can edit schedules in **Draft** status under **Light control > Schedules** and re-deploy them in cases where the deployment fails.

Hidden information in the emergency lighting test pdf report

This improvement ensures that all information within the emergency lighting test pdf report remains fully visible and is presented in a consistent format throughout the document.

### 5.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.12

  

Design software component	Version
Philips Dynalite System Designer	v4.47.17

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.47.17
Philips Dynalite Enabler app (iOS)	v3.17.0
Philips Dynalite Enabler app (Android)	v3.17.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.46.23156
PDDEG-S v3	v2.20.23154
PDDEG-S module	v1.0.45605

## 5.2. Resolved issues

The following issue is resolved in this Multisite System Manager release.

### 5.2.1. Energy dashboard UI performance issue

The **Energy dashboard** UI performance is fixed.

## 5.3. Known issues

### 5.3.1. Incorrect Notional energy data

**Description:** The **Notional** energy data is currently displaying data with a 2 days delay in the **Energy dashboard**.

**Workaround:** No workaround.

### 5.3.2. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 5.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 6. Build: 3.11

## 6.1. Build: 3.11

### 6.1.1. New feature

This Multisite System Manager release does not have any new features.

### 6.1.2. Enhancement/Improvement

This Multisite System Manager release does not have any enhancement/improvement.

### 6.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.11

  

Design software component	Version
Philips Dynalite System Designer	v4.46.4

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.46.4
Philips Dynalite Enabler app (iOS)	v3.16.0
Philips Dynalite Enabler app (Android)	v3.16.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.46.23156
PDDEG-S v3	v2.20.23154
PDDEG-S module	v1.0.45605

## 6.2. Resolved issues

This Multisite System Manager release does not have any resolved issues.

## 6.3. Known issues

### 6.3.1. Energy dashboard UI performance issue

**Description:** The **Energy dashboard** UI is currently experiencing significant performance issue. In some cases, loading times can extend up to 50 seconds, impacting the overall user experience.

**Workaround:** No workaround.

### 6.3.2. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 6.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

## 7. Build: 3.10

### 7.1. Build: 3.10

#### 7.1.1. New feature

This Multisite System Manager release does not have any new features.

#### 7.1.2. Enhancement/Improvement

##### Emergency test status

This improvement ensures that the status of all the connected emergency light test for all the connected sites are accurately represented in the **Assets > Dashboard > Emergency lighting tests** and **Assets > Site list > Emergency tests**

##### Emergency test filters

This improvement ensures that selecting any **Emergency lighting tests** status from **Assets > Dashboard** accurately filters the navigation to **Assets > Site list**.

#### 7.1.3. Supported infrastructure

##### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.10

  

Design software component	Version
Philips Dynalite System Designer	v4.46.4

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.46.4
Philips Dynalite Enabler app (iOS)	v3.16.0
Philips Dynalite Enabler app (Android)	v3.16.0

##### Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.46.23156
PDDEG-S v3	v2.20.23154
PDDEG-S module	v1.0.45605

## 7.2. Resolved issues

The following issue is resolved in this Multisite System Manager release.

### 7.2.1. Scaling in the energy dashboard

This fix ensures that the scaling of **All sites** in the **Energy dashboard** for a year is more accurate and optimized.

## 7.3. Known issues

### 7.3.1. Energy dashboard UI performance issue

**Description:** The **Energy dashboard** UI is currently experiencing significant performance issue. In some cases, loading times can extend up to 50 seconds, impacting the overall user experience.

**Workaround:** No workaround.

### 7.3.2. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 7.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

## 8. Build: 3.08

### 8.1. Build: 3.08

#### 8.1.1. New feature

This Multisite System Manager release does not have any new features.

#### 8.1.2. Enhancement/Improvement

View all historical results

This improvement ensures that all historical results of both **Functional tests** and **Duration tests** are consistently displayed in **View all historical results**.

Notional energy savings

This improvement ensures the accuracy of reporting the **Energy savings**, specifically for the combination of **Dim savings** and **Switch-off savings** under **Notional**.

#### 8.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.07

  

Design software component	Version
Philips Dynalite System Designer	v4.46.4

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.46.4
Philips Dynalite Enabler app (iOS)	v3.14.0
Philips Dynalite Enabler app (Android)	v3.14.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.44.22326
PDDEG-S v3	v2.18.22336
PDDEG-S module	v1.0.45605

## 8.2. Resolved issues

This Multisite System Manager release does not have any resolved issues.

## 8.3. Known issues

### 8.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 8.3.2. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 9. Build: 3.07

## 9.1. Build: 3.07

### 9.1.1. New feature

This Multisite System Manager release does not have any new features.

### 9.1.2. Enhancement/Improvement

#### Notional energy report

This improvement ensures a correct **Notional** energy report for the after sunset event in the **Energy** dashboard.

#### Emergency test results

This improvement ensures that the **Functional tests** results and the **Duration tests** results are displayed separately in **Assets > Site list > Emergency Tests > View details**.

#### Historical results

This improvement ensures that all historical results of both **Functional tests** and **Duration tests** are displayed in **Assets > Site list > Emergency Tests > View details > View all historical results**.

### 9.1.3. Supported infrastructure

#### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.07

  

Design software component	Version
Philips Dynalite System Designer	v4.46.2

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.46.2
Philips Dynalite Enabler app (iOS)	v3.13.0
Philips Dynalite Enabler app (Android)	v3.13.0

## Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.44.22326
PDDEG-S v3	v2.18.22336
PDDEG-S module	v1.0.43139

## 9.2. Resolved issues

The following issue is resolved in this Multisite System Manager release.

### 9.2.1. Browser compatibility issue

This fix ensures that no test results are missed in the report when downloading the Emergency lighting test report using **Google Chrome** browser.

## 9.3. Known issues

### 9.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 9.3.2. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 10. Build: 3.06

## 10.1. Build: 3.06

### 10.1.1. New feature

This Multisite System Manager release does not have any new features.

### 10.1.2. Enhancement/Improvement

#### Branding logo update

This improvement has led to a new logo update that is from "Interact" logo to "Signify Interact" logo.

#### Incorrect upcoming scenes indication

This improvement ensures a correct **Next scene (Local time)** indication in **Assets > Site list > Deployment & Scenes > Scenes** for all areas in a site.

#### Energy dashboard performance

This improvement optimizes the performance of the **Energy dashboard**, particularly when filtering data by **Week** or **Day** in the **Energy dashboard**.

### 10.1.3. Supported infrastructure

#### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.06

  

Design software component	Version
Philips Dynalite System Designer	v4.45.17

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.45.17
Philips Dynalite Enabler app (iOS)	v3.13.0
Philips Dynalite Enabler app (Android)	v3.13.0

## Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.42.21860
PDDEG-S v3	v2.16.21888
PDDEG-S module	v1.0.43139

## 10.2. Resolved issues

This Multisite System Manager release does not have any resolved issues.

## 10.3. Known issues

### 10.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 10.3.2. Browser compatibility issue

**Description:** When downloading the Emergency lighting test report through **Google Chrome** browser, there are missing test results in the report.

**Workaround:** Use **Microsoft Edge** to download the report.

### 10.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 11. Build: 3.05

## 11.1. Build: 3.05

### 11.1.1. New feature

Introduced a value package

Implemented a new seven-year value package for the Multisite System Manager.

### 11.1.2. Enhancement/Improvement

Emergency Tests tab

This enhances the visibility of the results within the **Emergency Tests** tab.

Inconsistent emergency test reports

This improvement ensures consistent data across all the auto-generated **Emergency lighting test report**.

### 11.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.05

  

Design software component	Version
Philips Dynalite System Designer	v4.45.17

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.45.17
Philips Dynalite Enabler app (iOS)	v3.12.0
Philips Dynalite Enabler app (Android)	v3.12.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.41.21102
PDDEG-S v3	v2.15.21110
PDDEG-S module	v1.0.43139

## 11.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 11.2.1. Performance issue

This fix ensures that no performance issue is observed when viewing the **Assets** dashboard and the **Energy** dashboard.

### 11.2.2. Emergency lighting test report pdf issue

This fix ensures that the auto-generated Emergency lighting test report pdf displays with correct pagination and properly formatted for printing.

## 11.3. Known issues

### 11.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** No workaround.

### 11.3.2. Browser compatibility issue

**Description:** When downloading the Emergency lighting test report through **Google Chrome** browser, there are missing test results in the report.

**Workaround:** Use **Microsoft Edge** to download the report.

### 11.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

## 12. Build: 3.04

### 12.1. Build: 3.04

#### 12.1.1. New feature

This Multisite System Manager release does not have any new features.

#### 12.1.2. Enhancement/Improvement

Enhanced connected Emergency lighting test experience

This improvement enhances the maturity of the licensing mechanism for connected Emergency lighting test.

#### 12.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.04

  

Design software component	Version
Philips Dynalite System Designer	v4.45.12

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.45.12
Philips Dynalite Enabler app (iOS)	v3.12.0
Philips Dynalite Enabler app (Android)	v3.12.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.41.21102
PDDEG-S v3	v2.15.21110
PDDEG-S module	v1.0.43139

## 12.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 12.2.1. Schedule deployment error

This fix ensures that no failure error is displayed when deploying a new site for the first time.

### 12.2.2. Missing Emergency test results in the cloud

This fix ensures that users can view the complete set of Emergency test results and do not miss any Emergency test results from any luminaires in a site.

## 12.3. Known issues

### 12.3.1. Performance issue

**Description:** When viewing the **Assets** dashboard and the **Energy** dashboard, slower loading performance is observed.

**Workaround:** Wait until the dashboard is loaded completely.

### 12.3.2. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** -

### 12.3.3. Browser compatibility issue

**Description:** When downloading the Emergency lighting test report through **Google Chrome** browser, there are missing test results in the report.

**Workaround:** Use **Microsoft Edge** to download the report.

### 12.3.4. Emergency lighting test report pdf issue

**Description:** When downloading the Emergency lighting test report, the auto generated pdf has a pagination issue and generates the report in one single page that could cause an issue if you want to print the report.

**Workaround:** Use the soft copy pdf report.

### 12.3.5. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

# 13. Build: 3.03

## 13.1. Build: 3.03

### 13.1.1. New feature

This Multisite System Manager release does not have any new features.

### 13.1.2. Enhancement/Improvement

#### Emergency Tests report update

This improvement has led to the following two updates on the emergency test report:

1. By default, only the latest **Functional tests** and **Duration tests** reports are displayed on the **Emergency Tests** tab page.
2. Use the **View details** option to view the historical **Functional tests** and **Duration tests** reports.

#### Battery (%) column

This improvement displays the correct battery health of the controller in the **Battery (%)** column whenever the **Test result** status is **Passed** in the **Emergency Tests** tab.

#### Status icon

This improvement displays the correct icon for each status in the **Test result** column in the **Emergency Tests** tab.

#### Site comparison data

This improvement corrects the visibility of all the **Metered** energy site comparison data in the **Energy** dashboard.

#### Energy trend data blocks

This improvement differentiates the color visibility of all the data blocks displayed on the **Energy trend** graph for **Metered** energy.

### 13.1.3. Supported infrastructure

#### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.03

Design software component	Version
Philips Dynalite System Designer	v4.44.18

Commissioning software component	Version
Philips Dynalite System Builder	v4.44.18
Philips Dynalite Enabler app (iOS)	v3.11.0
Philips Dynalite Enabler app (Android)	v3.11.0

### Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.41.21102
PDDEG-S v3	v2.15.21110
PDDEG-S module	v1.0.43139

## 13.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 13.2.1. Emergency lighting tests status redirecting issue

This fix ensures that when clicking on any of the **Emergency lighting tests** status in **Assets > Dashboard**, it should always redirect to the **Emergency Tests** tab in the **Assets > Site list** page.

### 13.2.2. Missing Emergency Tests status icon

This fix ensures that the status icon is always displayed beside the **Emergency Tests** tab.

### 13.2.3. Incorrect Emergency lighting test report data

This fix ensures that the Emergency lighting test report always generates a pdf report with only the latest test data.

### 13.2.4. Delay when viewing active scenes

This fix ensures that no delay is observed on viewing the **Active Scenes** in **Assets > Site list > Deployment & Scenes > Scenes**.

## 13.3. Known issues

### 13.3.1. Sorting issue of the Test result column

**Description:** When viewing all the historical data reports in the **Emergency Tests** tab, the sorting option of the **Test result** column is not working.

**Workaround:** -

### 13.3.2. Browser compatibility issue

**Description:** When downloading the Emergency lighting test report through **Google Chrome** browser, there are missing test results in the report.

**Workaround:** Use **Microsoft Edge** to download the report.

### 13.3.3. Emergency lighting test report pdf issue

**Description:** When downloading the Emergency lighting test report, the auto generated pdf has a pagination issue and generates the report in one single page that could cause an issue if you want to print the report.

**Workaround:** Use the soft copy pdf report.

### 13.3.4. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

### 13.3.5. Schedule deployment error

**Description:** When deploying a new site for the first time, the status displays a failure error upon deployment of the site.

**Workaround:** Deploy the site again.

# 14. Build: 3.02

## 14.1. Build: 3.02

### 14.1.1. New feature

This Multisite System Manager release does not have any new features.

### 14.1.2. Enhancement/Improvement

Enhanced connected Emergency lighting test experience

This improvement enhances the robustness of the licensing mechanism for connected Emergency lighting test.

### 14.1.3. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.02

  

Design software component	Version
Philips Dynalite System Designer	v4.44.16

  

Commissioning software component	Version
Philips Dynalite System Builder	v4.44.16
Philips Dynalite Enabler app (iOS)	v3.9.0
Philips Dynalite Enabler app (Android)	v3.9.0

Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.38.20160
PDDEG-S v3	v2.11.20158
PDDEG-S module	v1.0.42064

## 14.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 14.2.1. Duplicated values in Energy trend graph

This fix ensures that all values displayed on the **Energy trend** graph for **Metered** energy are correct.

### 14.2.2. Unable to select the Emergency Tests

This fix ensures that the **Emergency Tests** tab in **Assets > Site list > Emergency Tests** is always accessible.

### 14.2.3. Missing controller name

This fix ensures that the **Controller name** is always displayed in the emergency test report.

### 14.2.4. Incorrect color identification

This fix ensures that the **Energy consumption** and the **Energy trend** graph of **Metered** energy in the **Energy dashboard** shows correct color identification for all the **Meter groups**.

## 14.3. Known issues

### 14.3.1. Browser compatibility issue

**Description:** When downloading the Emergency lighting test report through **Google Chrome** browser, there are missing test results in the report.

**Workaround:** Use **Microsoft Edge** to download the report.

### 14.3.2. Emergency lighting test report pdf issue

**Description:** When downloading the Emergency lighting test report, the auto generated pdf has a pagination issue and generates the report in one single page that could cause an issue if you want to print the report.

**Workaround:** Use the soft copy pdf report.

### 14.3.3. Incorrect Emergency lighting test report data

**Description:** The Emergency lighting test report generates both latest and historical data that is incorrect.

**Workaround:** Use the test date to distinguish between latest test results and historical test results.

### 14.3.4. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

### 14.3.5. Delay when viewing active scenes

**Description:** A delay is observed on viewing the **Active Scenes** in **Assets > Site list > Deployment & Scenes > Scenes**.

**Workaround:** Select **Refresh** to reboot the scenes.

### 14.3.6. Schedule deployment error

**Description:** When deploying a new site for the first time, the status displays a failure error upon deployment of the site.

**Workaround:** Deploy the site again.

# 15. Build: 3.01

## 15.1. Build: 3.01

### 15.1.1. New feature

This Multisite System Manager release does not have any new features.

### 15.1.2. Enhancement/Improvement

#### Role management update

This improvement has led to the update of the user role management for better role clarity.

#### Enhanced login experience

This improvement enhances the robustness in commissioning.

#### Emergency pdf test report

This improvement includes the site name to the emergency pdf test report file name.

#### Updating the energy value concepts

This improvement enable users to read the **Energy consumed** and the **Energy saved** values as **n.a** instead of **0** whenever there is no data in **Energy > Site list**.

### 15.1.3. Supported infrastructure

#### Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.01

  

Design software component	Version
Philips Dynalite System Designer	v4.44.16

Commissioning software component	Version
Philips Dynalite System Builder	v4.44.16
Philips Dynalite Enabler app (iOS)	v3.9.0
Philips Dynalite Enabler app (Android)	v3.9.0

### Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.38.20160
PDDEG-S v3	v2.11.20158
PDDEG-S module	v1.0.42064

## 15.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 15.2.1. Updating the deployment details

This fix ensures that the **Format Manager** will also see the username who triggered the deployment in **Light control > Deployments > Deployed by**.

### 15.2.2. Discrepancy in the Test result summary

This fix ensures that the percentage of the **Functional tests** and the **Duration tests** successful rate is correct in the emergency pdf test report.

### 15.2.3. Negative values in Energy trend graph

This fix ensures that all values displayed on the **Energy trend** graph for **Notional > Energy saved** are positive values.

## 15.3. Known issues

### 15.3.1. Emergency lighting test report pdf issue

**Description:** When downloading the Emergency lighting test report, the auto generated pdf has a pagination issue and generates the report in one single page that could cause an issue if you want to print the report.

**Workaround:** Use the soft copy pdf report.

### 15.3.2. Incorrect Emergency lighting test report data

**Description:** The Emergency lighting test report generates both latest and historical data that is incorrect.

**Workaround:** Use the test date to distinguish between latest test results and historical test results.

### 15.3.3. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

### 15.3.4. Delay when viewing active scenes

**Description:** A delay is observed on viewing the **Active Scenes** in **Assets > Site list > Deployment & Scenes > Scenes**.

**Workaround:** Select **Refresh** to reboot the scenes.

### 15.3.5. Schedule deployment error

**Description:** When deploying a new site for the first time, the status displays a failure error upon deployment of the site.

**Workaround:** Deploy the site again.

### 15.3.6. Incorrect color identification

**Description:** The **Energy consumption** and the **Energy trend** graph of **Metered** in the **Energy dashboard** shows incorrect color identification for all the **Meter groups**.

**Workaround:** Clear all **Meter groups** checkboxes from the dropdown list except for the one that is of interest.

# 16. Build: 3.0

## 16.1. Build: 3.0

### 16.1.1. New feature

Connected emergency light test

This feature enables users to remotely monitor the status of all the connected emergency light test for all the connected sites in **Assets > Dashboard > Emergency Light tests**.



**Important**

This feature requires an additional Multisite Manager emergency add-on subscription to be purchased in addition to Multisite Manager standard subscription.

The following are the additional functionality of connected emergency light test:

1. **Monitor emergency test results:** It enables users to view the **Functional tests** and **Duration tests** result in **Assets > Site list > Emergency Tests**.
2. **Pdf test report:** It enables the user with **Facility manager** role to download the latest emergency test report in a pdf format for the selected site in **Assets > Site list > Emergency Tests**. This report provides the test summary details per emergency luminaire for the selected site.

For more information, see Emergency test.

### 16.1.2. Supported infrastructure

Supported software versions

Lists the latest software components versions supported in the Multisite System Manager.

Cloud services component	Version
Interact Multisite System Manager	v3.0

  

Design software component	Version
Philips Dynalite System Designer	v4.44.9

Commissioning software component	Version
Philips Dynalite System Builder	v4.44.9
Philips Dynalite Enabler app (iOS)	v3.8.0
Philips Dynalite Enabler app (Android)	v3.8.0

### Supported hardware's firmware versions

Lists the hardware's latest firmware versions supported in the Multisite System Manager.

Firmware component	Version
PDDEG-S v2	v1.38.20160
PDDEG-S v3	v2.11.20158
PDDEG-S module	v1.0.42064

## 16.2. Resolved issues

The following issues are resolved in this Multisite System Manager release.

### 16.2.1. Missing deployment details

This fix ensures that the deployment details are always displayed for all the sites in **Light control** tab.

## 16.3. Known issues

### 16.3.1. Improvement on schedule implementation

**Description:** Currently all schedule implementation are disabled during the night and it could impact on the emergency test schedules.

**Workaround:** Review the commissioning with respect to disabled schedules, and ensure that the emergency test schedules are enabled.

### 16.3.2. Delay when viewing active scenes

**Description:** A delay is observed on viewing the **Active Scenes** in **Assets > Site list > Deployment & Scenes > Scenes**.

**Workaround:** Select **Refresh** to reboot the scenes.

### 16.3.3. Schedule deployment error

**Description:** When deploying a new site for the first time, the status displays a failure error upon deployment of the site.

**Workaround:** Deploy the site again.

### 16.3.4. Incorrect color identification

**Description:** The **Energy consumption** and the **Energy trend** graph of **Metered** in the **Energy dashboard** shows incorrect color identification for all the **Meter groups**.

**Workaround:** Clear all **Meter groups** checkboxes from the dropdown list except for the one that is of interest.

Learn more about Interact  
[www.interact-lighting.com](http://www.interact-lighting.com)

© 2026 Signify Holding. All rights reserved.

The information provided herein is subject to change, without notice. Signify does not give any representation or warranty as to the accuracy or completeness of the information included herein and shall not be liable for any action in reliance thereon. The information presented in this document is not intended as any commercial offer and does not form part of any quotation or contract, unless otherwise agreed by Signify.

All trademarks are owned by Signify Holding or their respective owners.